

Hot Melt Termination Tool Kit



Install Hot Melt fiber optic connectors —no epoxy, no mess.

FEATURES

- Use to terminate Hot Melt ST®, SC, and FC connectors.
- Included Hot Melt Oven heats the connector adhesive to the exact temperature, bonding it securely to the fiber cable.
- Oven heats up fast—ready to use in less than four minutes.
- Heater block ensures the precise amount of heat transfer and helps the oven to cool down quicker.
- Built-in cooling tower.

WHAT'S INCLUDED

- ◆ 6-Port Hot Melt Oven (FT655)
- ◆ Universal connector holders
- ◆ Holder handles
- ◆ 100X microscope
- ◆ Safety glasses
- ◆ Scribe
- ◆ Crimp tool with 3M die set
- ◆ Jacket stripper
- ◆ Buffer stripper
- ◆ Pair of electrician's scissors
- ◆ Marker
- ◆ Ruler
- ◆ Polishing pads
- ◆ 1- μ m polishing film
- ◆ Stainless Steel Polishing Fixture for ST, SC, and FC (FT652)
- ◆ Canned air dispenser
- ◆ Water bottle
- ◆ 120-ft. roll of masking tape
- ◆ Soft, lint-free wipes
- ◆ Alcohol-soaked pads
- ◆ Alcohol dispenser bottle
- ◆ Flip-top debris bottle
- ◆ Plastic box, utility pouch, and tool roll
- ◆ Templates and manuals
- ◆ Hard shell case with keys

Item	Code
Hot Melt Termination Tool Kit	FT650
You may also need...	
Hot Melt Connector ST Multimode with White Boot	FO020
You can also order the oven by itself...	
6-Port Hot Melt Oven	FT655
For polishing ST, SC, and FC Hot Melt connectors, we offer...	
Polishing Fixture	
Co-Polymer	FT654
Stainless Steel	FT652
To use your kit with LC connectors, order...	
LC Polishing Puck, Stainless Steel	FT653