

QUICKSTART GUIDE

EVO TP6 POS Terminal

1

Accessing Ports and Connecting Power

- Remove the two part cable cover as shown below
- Locate power supply in the accessory box
- Connect the power supply to the **GREEN** 'DC 19V in' port and a power outlet



2

Connecting LAN Cable and other devices

- Locate network cable (not supplied)
- Connect cable to **RED** 'LAN' port
- Connect any other devices to the appropriate ports

WARNING: Do not connect any other type of cable to the "LAN" port as it may cause damage not covered by warranty.



3

Route Cables


- Remove the cable cover as shown below
- Route cables through base



4

Replace Covers

- Replace all cable covers removed in previous steps



5

Power On

- The TP6 power button is located on the right side of the screen



Port Diagram - EVO TP6 J1900



Port Diagram - EVO TP6D/W

