



## Cleaning and replacing the separation roller



## Support Information

[www.AlarisWorld.com/go/E1025support](http://www.AlarisWorld.com/go/E1025support)  
[www.AlarisWorld.com/go/E1035support](http://www.AlarisWorld.com/go/E1035support)

When contacting support, have the following available:

- A description of your problem
- Scanner model and serial number
- Computer configuration
- Software application you are using

## Cleaning the imaging area



## Supplies and Consumables

[www.AlarisWorld.com/go/E1025support](http://www.AlarisWorld.com/go/E1025support)  
[www.AlarisWorld.com/go/E1035support](http://www.AlarisWorld.com/go/E1035support)

© 2018 Kodak Alaris Inc.  
TM/MC/MR: Alaris  
A-61908 / Part #5K7834 September 2018

All trademarks and trade names used are the property of their respective holders. The Kodak trademark and trade dress are used under license from Eastman Kodak Company.



5K7834



# Alaris

## E1000 Series Scanners




Reference Guide



## Cleaning the rollers



## Cleaning the feed rollers



## Cleaning and replacing the separation roller

